

Installation instructions for UANGM-02932-00, UANGM-02933-00
Under Run Protective Shield Engine Bay

TOYOTA Hilux



TOYOTA Fortuner



Model year:

Applicability:

Part Number:



Weight:



Installation Time:

Hilux

2015-

GUN125L-DTFSHW;
GUN125L-DTFMHW
GUN126L-DTTMHW;
GUN126L-DTTHHW

Fortuner


2017-

GUN156L-STTMH
GUN156L-STTSH
TGN156L-STTSKK
TGN156L-STMLKK



Steel: UANGM-02932-00
Aluminium: UANGM-02933-00


Steel: 10.93 kg
Aluminium: 6.01 kg

30 min



UANGM-02932-60



B  M8x30 6x	C  d=8 6x	D  d=8 6x
--	---	--



13 mm





1





see repair manual





2




3



4




5



FWD ↑



A1

13 mm




C
D
B

C
D
B



6



FWD ↑

